






REPLACEMENT SHEET

1/8



IMPROVEMENTS TO A BLOOD COLLECTION DEVICE
DON CHANNER
SERIAL NO. 10/587,139
ATTORNEY DOCKET NO. CUL-0023
Cantor Colburn LLP, 20 Church Street, 22nd Floor, Hartford, CT 06103
REPLACEMENT SHEET

2 / 8



REPLACEMENT SHEET

A detailed cross-sectional view of a mechanical assembly, likely a pump or valve. The assembly is shown in a half-section view, with the right half hatched to indicate it is a solid part. The central component is a shaft (1b) passing through the assembly. The shaft is supported by bearings (2a, 2b) and has a central impeller or valve (2c). The impeller is connected to a drive shaft (3a, 3b). The drive shaft is connected to a motor or actuator (46, 47). The entire assembly is housed within a casing (5, 5b, 5c, 5d). The casing has a flange (5b) and a mounting bracket (5c). The assembly is shown in a perspective view, with the shaft (1b) extending from the left side.

FIG 6B

REPLACEMENT SHEET

4 / 8




FIG 7A




FIG 7C




FIG 7B




FIG 8

REPLACEMENT SHEET




FIG 9




FIG 10




FIG 11

IMPROVEMENTS TO A BLOOD COLLECTION DEVICE
DON CHANNER
SERIAL NO. 10/587,139
ATTORNEY DOCKET NO. CUL-0023
Cantor Colburn LLP, 20 Church Street, 22nd Floor, Hartford, CT 06103
REPLACEMENT SHEET




FIG 12




FIG 13




FIG 14

REPLACEMENT SHEET




FIG 15




FIG 16




FIG 17

IMPROVEMENTS TO A BLOOD COLLECTION DEVICE
DON CHANNER
SERIAL NO. 10/587,139
ATTORNEY DOCKET NO. CUL-0023
Cantor Colburn LLP, 20 Church Street, 22nd Floor, Hartford, CT 06103

REPLACEMENT SHEET

8/8




FIG 18